

Not e: The stability of the structure should be examined also with reference to location, Altitude, intensity of wind, exposure of flood etc, 2. Any additional observations if deemed Necessary for the certificate may be furnished separately with the certificate.

CERTIFICATE

Certified that the school building was inspected by me 28/08/19 on and found to be fit to Conduct classes, for the period year 2019-2020, 2020-2021 for the reasons stated above.

Place:- Satna

Date:- 29/08/19

Copy forwarded to:-

1. ✓ Manager, Blooms Academy School


NISHANT SINGH
(B.Arch.)
CA/2016/78646